

Achizitie directa initiata din catalogul electronic

Cod unic achizitie: DA26739379

Informatii generale	
DENUMIRE ACHIZITIE: REVIZIE SI REPARATIE BULDOEXCAVATOR JCB 2CX	Data publicare: 04.11.2020 13:46
Cod si denumire CPV: 50111000-6 Servicii de gestionare, de reparare si de intretinere a parcurilor de vehicule (Rev.2)	Data finalizare: 06.11.2020 12:35
Finantare prin fonduri comunitare: Nu	Data de raspuns a ofertantului: 05.11.2020 11:19
Tip de contract: Servicii	Data de raspuns a autoritatii contractante: 06.11.2020 12:35
Stare: Oferta acceptata	

Autoritatea contractanta	Operator economic
Denumire: SECOM S.A. - DROBETA TURNU SEVERIN	Denumire: ELYTTE BUILDING SRL
CUI: 1605884	CUI: 15549881
Adresa: Strada: Carol I, nr. 53, Sector: -, Judet: Mehedinti, Localitate: Drobeta-Turnu Severin, Cod postal: 220146	Adresa: Strada: Numa Pompiliu, nr. 1, Sector: -, Judet: Mehedinti, Localitate: Drobeta-Turnu Severin, Cod postal: 220118
Localitatea, Tara: Drobeta-Turnu Severin, Romania	Localitatea, Tara: Drobeta-Turnu Severin, Romania
Telefon: +40 352401330	Telefon: +4 722684602
E-mail: achizitii publice@secom-mehedinti.ro	E-mail: elyttebuilding@yahoo.com
Website: www.secom-mehedinti.ro	

Informatii cumparare directa	
Descriere	1Rep.ps schimb,manop, punte fata,punte spate,brat fat,brat spate,cupa fata,cupa spate-bucse-1 buc x200Ron-bucse-2bucx150Ron-bucse 2bucx300Ron-bucse 2bucx400Ron-bucse4bucx80Ron-bucse 2bucx80Ron-bucse brat 4bucx80Ron-bucse 2bucx50Ron-simering 12bucx50Ron-patine drept brat telescopic 4bucx150Ron-patine tra.brat telescopic 4bucx200Ron-placa metalica patine 4bucx50Ron-Punte fata-demontat,rep,rectif prin frezare punte fata-confbolturi-3buc-montat-manopera-1500Ron-Punte spate-demontat,rep,rectif prin frezare punte spate-confectionare bolturi-3buc-montat-manopera-1500Ron-Brat fata-demontat,rep,rectif prin frezare brate fata-confectionare bolturi-16buc-confectionat bucse-12buc-montat-manopera-5400Ron-Brat spate-Demontat,rep,rectif prin frezare brate spate-confectionare bolturi-14buc-confectionat bucse-10buc-montat-manopera-4800Ron-Cupa spate-demontat,rep,rectif prin frezare si schimbare placa de uzura-confectionat bucse-4buc-montat-manopera-1400Ron-Cupa fata-demontat,reparatie,rectificare prin frezare si schimbare placa de uzura-confectionat bucse-4 buc-confectionat bolturi-4buc-montat-manopera-1400Ron 2Schimb ulei-ulei cutie viteza-7 lx30 Ron-ulei transmisie finala 75W80-16 lx50Ron-ulei punte spate 75W90-15lx70Ron-ulei punte fatA75W80-15LX50Ron-ulei comenzi hidraulice 15W40 20L-4 bucX250Ron-ulei motor 10W40 5L-4bucx200Ron-ulei frana ATF-2LX60Ron-filtru ulei motor-1bucx100Ron-filtru hidraulic-1bucx100Ron-filtru aer-1buc x200Ron-filtru comb-1bucx150Ron-manop schimb ulei-800Ron
Conditii de livrare	LA SEDIUL PRESTATORULUI
Conditii de plata	OP LA TERMEN

Repere achizitionate	Cantitate	Valoare achizitie (RON fara TVA)
REVIZIE SI REPARATIE BULDOEXCAVATOR JCB 2CX	Solicitata: 1	Pret estimat: 27.080,00

Numar de referinta: 0016	Ofertata: 1	Pret de vanzare: 27.080,00
Pret de catalog: 27.080,00 RON/bucata		Valoare estimata: 27.080,00
Cod si denumire CPV: 50100000-6 - Servicii de reparare si de intretinere a vehiculelor si a echipamentelor aferente si servicii conexe (Rev.2)		Valoare de vanzare: 27.080,00
<p>Descriere: 1.Reparatie,piese schimb,manopera, punte fata,punte spate,brat fat,brat spate,cupa fata,cupa spate</p> <ul style="list-style-type: none"> -bucse-1 buc x200 Ron -bucse-2bucx150 Ron -bucse 2bucx300 Ron -bucse 2bucx400 Ron -bucse4bucx80 Ron -bucse 2bucx80 Ron -bucse brat 4bucx80 Ron -bucse 2bucx50 Ron -simering 12bucx50 Ron -patine drept brat telescopic 4bucx150 Ron -patine tra.brat telescopic 4bucx200 Ron -placa metalica patine 4bucx50 Ron - Punte fata- demontat,reparatie,rectificat prin frezare punte fata -confectionare bolturi-3buc -montat-manopera-1500 Ron -Punte spate- demontat,reparatie,rectificat prin frezare punte spate -confectionare bolturi-3buc -montat-manopera-1500 Ron -Brat fata- demontat,reparative,rectificat prin frezare brate fata -confectionare bolturi-16buc -confectionat bucse-12 buc -montat-manopera-5400 Ron - Brat spate- demontat,reparative,rectificat prin frezare brate spate -confectionare bolturi-14buc -confectionat bucse-10 buc -montat-manopera-4800 Ron -Cupa spate- demontat,reparatie,rectificare prin frezare si schimbare placa de uzura -confectionat bucse-4 buc -montat-manopera-1400 Ron -Cupa fata- demontat,reparatie,rectificare prin frezare si schimbare placa de uzura -confectionat bucse-4 buc -confectionat bolturi-4 buc -montat-manopera-1400 Ron <p>2.Schimb ulei</p> <ul style="list-style-type: none"> -ulei cutie viteza-7 l x30 Ron -ulei transmisie finala 75W80 -16 l x50 Ron -ulei punte spate 75W90 - 15 L x70 Ron -ulei punte fata 75W80 - 15 LX50 Ron -ulei comenzi hidraulice 15W40 20 L-4 buc X250 Ron -ulei motor 10W40 5 L-4 buc x200 Ron -ulei frana ATF-2 L X60 Ron -filtru ulei motor-1 buc x100 Ron -filtru hidraulic-1 buc x100 Ron -filtru aer- 1 buc x200 Ron -filtru combustibil -1 buc x 150 Ron -manopera schimb ulei-800 Ron 		
TOTAL		Valoare de vanzare: 27.080,00 RON